Number : DQF.01 Revision : 03 Effectivity Date : 09/2020 Page 1 of 4

TITLE SUPPLIER QUALITY SYSTEM REQUIREMENTS FOR MAINTENANCE SERVICES ORGANIZATIONS

This appointion the					
This specification applies to aerospace suppliers and their subcontractors who furnish product, material processes, or services (as a maintenance provider) to Patria BEC as a contract requirement regardless of supplier's industry, regulatory accreditation, or certification status. (Type A & B)					
This document defines the quality system requirements for suppliers who provide maintenance services.					
This document is the property of Patria BEC. You may not possess, use, copy or disclose this document or any information in it, for any purpose, including without limitation to design, manufacture, or repair parts, or obtain government approval to do so, without Patria BEC express written permission. Neither receipt nor possession of this document alone, from any source, constitutes such permission. Possession, use, copying or disclosure by anyone without Patria BEC express written permission is not authorized and may result in criminal and/or civil liability.					
Control of Quality Records is a process that implicates export control considerations and that accordingly contains steps to ensure compliance with applicable export and sanctions laws. Patria BEC employees must follow these steps in accordance with the export outlined. If you do not understand your export obligations or require further assistance, please contact your local BAER for assistance.					
Edition Date	Rev.	§ Changed	Description of the Change		
11/2016	01		Document creation		
12/2017	02		Add DQF 05 reference since DQF 02 was split in two procedures		
09/2020	03	See margin	Add EMAR 145 requirements		
Chapitre Titre					
Chapter I	rement				
Document & Section Title					
None					
Process Owner: Quality Manager (PS10 : Insure Product Quality)					
Document Custodian: Quality Manager					
Publication No	tificatio	n: QPulse			
The following references support the implementation of this document:					
Reference Title					
DQF.02 Supplier Quality Requirements for product subcontractors					
DQF.05 Supplier Quality Requirements for brokers & distributors					
None					
Authorized Release Certificate	Release Certificate (ARC) provides evidence that products or articles are approved for				
Contracted	А	supplier that h	olds a valid and current certificate from an appropriate National		
	of supplier's ind This document This document is ti in it, for any purpo- do so, without Pats source, constitutes permission is not a Control of Quality I ensure compliance with the export out local BAER for ass Edition Date 11/2016 12/2017 09/2020 Chapitre Chapter I Document & S None Process Owne Document Cuss Publication No The following re Reference DQF.02 DQF.05 None Authorized Release Certificate	of supplier's industry, res This document defines t This document is the propert in it, for any purpose, includi do so, without Patria BEC es source, constitutes such perr permission is not authorized Control of Quality Records is ensure compliance with appli with the export outlined. If you local BAER for assistance. Edition Date Rev. 11/2016 01 12/2017 02 09/2020 03 Chapitre Titre Chapter I Supple Document & Section None Process Owner: Quality Document Custodian: Publication Notification The following references Reference I DQF.02 S None Authorized Alis Release Ca Certificate rel he ea ide	of supplier's industry, regulatory accred This document defines the quality syste This document is the property of Patria BEC. Yin it, for any purpose, including without limitati in it, for any purpose, including without limitati do so, without Patria BEC express written posource, constitutes such permission. Possessi permission is not authorized and may result in Control of Quality Records is a process that in ensure compliance with applicable export and with the export outlined. If you do not understatiocal BAER for assistance. Edition Date Rev. § Changed 11/2016 01 1 12/2017 02 0 09/2020 03 See margin Chapter I Supplier QMS requi Document & Section None Process Owner: Quality Manager (PS Document Custodian: Quality Manager (PS S Supplier Quality DQF.05 None Authorized Also referred to Certificate (ARC) r		

	National Aviation Authority:	May be civil or military. This is the governing body of each respective country, or union of countries, which establishes rules, laws, guidance and other requirements of all things related to commercial or military aviation, including maintenance and overhaul of aircraft registered in the respective country.	
	Maintenance Services:	Work performed per approved technical data as required by customer or regulatory requirements.	
	Subcontracte organisation	d A supplier that either holds no certificates from a National Aviation Authority (NAA) or does not hold one from the NAA needed for the part or article or is not appropriately rated.	
	Supplier/ Provider:	An entity that provide products or services to a contract.	
	Type A - Deal Stockist, Distributor, Catalogue, Standard.	er, Supplier of an article or material which complies with a specification published by the Supplier, an industry or a recognized national authority of which all characteristics are defined in a text, a civil or military normative definition or a catalogue. Supplier with control over the product's design. They are responsible for the technical definition of a product or article and its technical management.	
	Type B - Aeronautical Maintenance Supplier	Supplier of a service for review, repair, inspection, replacement, change or correction of a component, carried out after production and initial airworthiness certificate from the relevant Authority.	
Acronyms	The following defined acronyms are used throughout this document		
(Optional)	Acronym - Se	e	
	CAA	Civil Aviation Authority	
	СВ	ertified Body	
	NAA	National Aviation Authority	
OASIS		Online Aerospace Supplier Information Center	
	QMS	Quality Management system	

CHAPTER I SUPPLIER QMS REQUIREMENTS

Requirements

- Suppliers and their subcontractors shall understand and comply with Patria BEC Quality Management System (QMS) requirements.
- Certificated suppliers shall comply with applicable QMS requirements. Supplier Certificate(s) of Registration to applicable QMS assessments shall be issued by a Certification Body (CB).
- The CB must be accredited under the control of the International Aerospace Quality Group (IAQG) certification/registration schemes, as recognized by the Aerospace Standard SAE AS 9104. Reference the IAQG website for a listing of accredited CBs.
- Suppliers shall permit Patria BEC access to all data in the Online Aerospace Supplier Information Center (OASIS) data base including registration documentation, certification, audit reports, findings, corrective actions, etc. Patria BEC reserve the right to input significant and/or frequent escape data and major audit findings regarding suppliers into the relevant OASIS data base records for those suppliers.
- Non-certificated suppliers shall comply with Patria BEC requirements. Non-certificated suppliers
 may be subject to QMS audits by Patria BEC and required to reimburse Patria BEC for the cost of
 conducting these audits until certification / registration / accreditation is achieved.
- Suppliers shall provide Patria BEC with notification of any changes in the certification / registration / accreditation/ transfer of work or major audit findings within 2 business days of receiving notification of the change or finding. Examples of changes in registration include new certification, suspension, or expiration.
- Patria BEC, its representatives, its customers, and its customer's governmental agencies or regulatory agencies shall have the right of entry into a supplier's facility or that of their subcontractors. Entry shall provide for access to quality system documentation, quality records as well as the ability to conduct audits, verify product and processes.
- Suppliers shall comply with applicable commercial, military and customer requirements and regulation.
- Distributors or organizations carrying out the purchase, storage, splitting and sale of products without affecting product conformance may be registered to the SAE AS/EN/JISQ 9100 series. Noncertificated distributors shall comply with Patria BEC requirements.
- Parts must be certified using a Certificate of Conformance or Civil Aviation Authority Form release certificate as required by Patria BEC or customer requirements.

Record Keeping Completed Quality records generated electronically or on paper shall be retained per Patria BEC defined in DQF.02, DQF.05 or Civil Aviation Authority requirement whichever is greatest.

Reference

It is the responsibility of the supplier to obtain copies of non–Patria BEC documents specified herein. These include, but may not be limited to the following:

Document	Title
SAE AS9100	Quality Management Systems –Requirements for Aviation, Space and Defense Organizations
SAE AS9104	Requirements for Aviation, Space, and Defense Quality Management System Certification Programs
SAE AS9110	Quality Management Systems – Requirements for Aviation Maintenance Organizations
SAE AS9120	Quality Management Systems – Requirements for Aviation, Space and Defense Distributors